Programmes After Market Services
APPX 1 NHP–4 Transceiver

Mechanical Assy

Issue 1 04/99

CONTENTS

Page No

Exploded View . . . . . 2 – 3
Assembly Parts . . . . . 2 – 4

Exploded View NHP–4



4

Assembly Parts

No.	Description	Codes	Qty.
1	Antenna	0660169	1
2	A–Cover Module Warm Black (w/ ESD Pl.)	9450269	1
3	B–Cover (w/ ”NOKIA”)	9450504	1
4	Chassis with Gasket	9547003	1
5	Shield with Gasket	9467020	1
6	Window	9457246	1
7	Screw M2X5–BT ZNB TORX6	6290060	4
8	Screw ZN 1.8X9 TORX6 PAN–HEAD	6291921	6
9	Main Keymat	9790154	1
10	Power Key	9790062	1
11	Side Key	9790055	1
12	Tape 57mm Wide Polethylene Blue (not shown)	9380494	1
13	Type Label(Con. Sheet) 4D23435 38X44.5	9380264	1
14	System Connector Cover	9457112	1
T1	UIF Flexible PCB module	0200521	1
T2	System Module	0200996	1